935 SMITHFIELD AVE

Location 935 SMITHFIELD AVE

Mblu 06/213/0//

Acct# 14-04957-01

Owner 935 SMITHFIELD AVENUE LLC

Assessment \$491,800

Appraisal \$491,800

PID 714

Building Count 2

Current Value

	Appraisal				
Valuation Year	Improvements	Land	Total		
2016	\$338,100	\$153,700	,700 \$491,80		
	Assessment				
Valuation Year	Improvements	Land	Total		
2016	\$338,100	\$153,700	\$491,800		

Owner of Record

Owner

935 SMITHFIELD AVENUE LLC

Sale Price

\$0

Co-Owner Address Certificate

D. I. O. D.

Book & Page 001950/000229

300 FRONT ST Sale Date

LINCOLN, RI 02865

06/22/2015

Instrument 14

Ownership History

Ownership History						
Owner Sale Price Certificate Book & Page Instrument Sale Date						
935 SMITHFIELD AVENUE LLC	\$0		001950/000229	14	06/22/2015	
935 SMITHFIELD AVENUE LLC	\$10,000		001949/000241	12	06/16/2015	
FAIRLAWN OIL SERVICE INC	\$0		0/0	50	01/01/1754	

Building Information

Building 1 : Section 1

Year Built:

1955

Living Area:

2,100

Replacement Cost:

\$296,607

Building Percent

65

Good:

-

Replacement Cost

Less Depreciation:

\$192,800


Building Attributes				
Field Description				
STYLE	Gas Ser w/ Retail			
MODEL	Comm/Ind			
Grade	1.00			
Stories	1.00			
Occupancy	1.00			
Exterior Wall 1				
Quality	Avg			
Exterior Wall 1				
Exterior Wall 2				
Roof Structure	Flat			
Roof Cover	Rubber			
Interior Wall 1	Drywall or Plaster			
Interior Wall 2				
Interior Floor 1	Tile			
Building Class	С			
Heating Fuel	Oil			
Cns Struct Class				
Building Use	Large Bus Mdl-94			
Cooling	Central			
Cooling Percent	100			
Interior Floor 2				
Plumbing Adequacy	Typical			
Total Fixtures	0			
1st Floor Use				
Heat 1	Warm Air			
Ext Wall 1	Combination			
Heat 1 Pct	100			
Heat 2				
Heat 2 Pct	0			
Wall Height	16.00			
Frame Type	Conc. / CB			

Building Photo



(http://images.vgsi.com/photos2/LincolnRIPhotos///06_213.0_C/

Building Layout



Building Sub-Areas (sq ft)			Legend
Code	Description	Gross Area	Living Area
BAS	First Floor	2,100	2,100
CPY	Canopy	523	0
		2,623	2,100

Building 2 : Section 1

Year Built:

1981

Living Area:

Replacement Cost:

2,360

Building Percent

\$136,964 66

Good:

Replacement Cost


Less Depreciation:

\$90,400

Building Attributes : Bldg 2 of 2


Field	Description
STYLE	GARAGE, SERVICE
MODEL	Comm/Ind
Grade	1.00
Stories	1.00
Occupancy	1.00
Exterior Wall 1	
Quality	Avg
Exterior Wall 1	
Exterior Wall 2	
Roof Structure	Flat
Roof Cover	Metal
Interior Wall 1	Unfinished
Interior Wall 2	
Interior Floor 1	Concrete
Building Class	S
Heating Fuel	Oil
Cns Struct Class	
Building Use	Large Bus Mdl-94
Cooling	
Cooling Percent	0
Interior Floor 2	
Plumbing Adequacy	Typical
Total Fixtures	0
1st Floor Use	
Heat 1	Warm Air
Ext Wall 1	Metal
Heat 1 Pct	100
Heat 2	
Heat 2 Pct	0
Wall Height	14.00
Frame Type	Steel

Building Photo



(http://images.vgsi.com/photos2/LincolnRIPhotos//default.jpg)

Building Layout



Building Sub-Areas (sq ft)			Legend	
Code	Description	Gross Area	Living Area	
BAS	First Floor	2,360	2,360	
		2,360	2,360	

Extra Features

Extra Features	<u>Legend</u>
No Data for Extra Features	

Land

Use Code

333

Description

Large Bus MdI-94

Zone

BL05

Neighborhood CC

Alt Land Appr No

Category

Size (Acres) 0.49

Frontage

Depth

Assessed Value \$153,700

Appraised Value \$153,700

Outbuildings

Outbuildings <u>Lege</u>					Legend	
Code	Description	Sub Code	Sub Description	Size	Value	Bldg #
0062	Paving	1001	Asphalt/sqft	35000.00 01	\$22,800	1
GCPY	CPY - GAS	08	Metal	1116.00 01	\$32,100	1

Valuation History

Appraisal				
Valuation Year	Improvements	Land	Total	
2016	\$282,500	\$141,200	\$423,700	
2015	\$282,500	\$141,200	\$423,700	

Assessment				
Valuation Year	Improvements	Land	Total	
2016	\$282,500	\$141,200	\$423,700	
2015	\$282,500	\$141,200	\$423,700	

(c) 2016 Vision Government Solutions, Inc. All rights reserved.